					WARRANT CONC. II. PERIOTERA NADA I	THE RESIDENCE OF STREET, AND ADDRESS OF THE PROPERTY OF THE PR			i i i i i i i i i i i i i i i i i i i	
					Dale II	Description *	Corrective Action	Goments	RB Action	County
Burch Group,	Prunedale Shopping Center		Water Quality -> Effluent ->	WDR		Chronic effluent pH violations. Permit limit range 6.4 to 8.4. Reported value is 6.1 on 02/08/2008, 6.3 on 02/15/2008, 6.2 on 02/19/2008 and 6.0 on	Staff will address	Based on a field investigation, low pH probably from food-related facilities' septic tanks. New treatment plant to be built this year should eliminate low pH through aerobic treatment process.		Monterey
The	Prunedale Shopping		Water Quality -> Effluent ->	VVDIC	,	Chronic effluent pH violations: Permit limit 6.4 to 8.4. Reported value is 6.2 on 03/07/2008 &		Based on a field investigation, low pH probably from food-related facilities' septic tanks. New treatment plant to be built this year should eliminate low pH through aerobic		
The	Center	749866		WDR	14-Mar-08		with an NOV.	treatment process. Although the	<u> </u>	Monterey
Ca Army National Guard	Camp Roberts STP	753851	Water Quality -> Effluent -> CAT1 Water	WDR	4-Mar-08	Nitrate Violation: Limit is 7.7 mg/L and the reported value is 9.8	Discharger is improving practices. Nitrate trend is down from 16 mg/L to the current 9.8 mg/L in the past 6 months.	concentration exceeds the limit, the total mass is much less than allowed under the WDRs because the flows are 0.040 MGD instead of 1.0 MGD.		Monterey
Ca State Parks	Rig Rasin CS	744034	Quality -> Sanitary Sewer Overflow/	WDR	22-Mar-08	Root intrusion blockage caused a 50 gallon sewage spill at Big Basin State Park from a manhole to the ground. No waterbody was affected.		No further action recommended at this time.		Santa Cruz
Carmel Area	Carmel Area Wastewater		Quality -> Sanitary Sewer Overflow/	WDR		Root intrusion caused a 135 gallon sewage spill at Carmel Knolls Dr. from a manhole at back easement. No waterbody was affected.	cleaned up. Discharger developing Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey
WWD Carmel Area WWD	Carmel Area Wastewater Dist CS	721834 736298	Quality -> Sanitary Sewer Overflow/	WDR		Debris blockage caused a 50 gallon sewage spill at 25750 Carmel Knolls Dr. from a private lateral to the ground. No waterbody was affected.	Spill and area cleaned up. Discharger developing Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey

					organización Profesional Profesional			Krit Akin	RB Action	County
Carmel Area	Carmel Area Wastewater Dist CS		Quality -> Sanitary Sewer Overflow/	WDR		Root intrusion blockage caused 85 gallon sewage spill at 3410 Martin Rd. from a manhole to the ground. No waterbody was	Spill and area cleaned up. Discharger developing Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey
			Water Quality -> Effluent ->			pH Violation: limit range is pH 6.50 to 8.4. Reported pH was	None	Appears to be anomalous result. Will check future reports.		Santa Clara
Casa De Fruta	Casa De Fruta	722946	OEV Monitoring	WDR	4-Feb-08	6.32.	None			Garita Giara
Cuyama Community Services District	Cuyama CSD WWTP	738196	-> Deficient Monitoring	NPDES	1-Feb-08	Failure to report annual acute toxicity.		diddital gott	NOV	Santa Barbara
Cypress Ridge	Cypress Ridge	755258	Water Quality -> Effluent ->	WDR		Residual chlorine violation. Minimum residual limit 0.5mg/L. Reported value for chlorine residual was 0.3mg/L.	Compliance plan submitted 3/21/08	Abatement Order Issued regarding similar violations, compliance plan has been submitted but not yet implemented.	CAO	San Luis Obispo
Cypress Ridge	Cypress Ridge	744716	Water Quality -> Effluent ->	WDR		Turbidity Violation: Limit must not exceed 5 NTU 5% of the time. Reported values indicate 5 NTU >5% of the time recorded on 2/19/2008.	Compliance plan submitted 3/21/08.	Cleanup and Abatement Order issued regarding similar violations, compliance plan has been submitted but not yet	CAO	San Luis Obispo
Cypress Ridge	Cypress Ridge	744725	Water Quality -> Effluent ->	WDR	15-Feb-08	Total Residual Chlorine Violation: limit must be greater than or equal to 0.5 mg/L. Reported values were below 0.5 mg/L on 2/7, 2/11	Compliance plan submitted 3/21/08	Cleanup and Abatement Order issued regarding similar violations, compliance plan has been submitted but not yet	CAO	San Luis Obispo
Cypress Ridge	Cypress Ridge		Water Quality -> Effluent ->			Turbidity Violation: Mean NTU limit is 2. Reported values indicate NTU greater than 2 on 2/1-2/9, 2/13, 2/16, 2/19-2/23 and 2/26.	Compliance plan submitted 3/21/08.	Abatement Order issued regarding similar violations, compliance plan has been submitted but not yet implemented.	CAO	San Luis Obispo
Gilroy, City of	Gilroy CS	736511	Water Quality -> Sanitary Sewer Overflow/	WDR	8-Mar-08	Rags and 4 plastic balls caused a blockage resulting in a 40 gallon grey water sewage spill at El Cerrito Street to the ground. No waterbody was affected.	None	No further action recommended at this time.		Santa Clara

						ellera : ellera :	Corrective Lacius	Comments and	RB 4.1 Action	County
	Gilroy CS	741158	Quality -> Sanitary Sewer Overflow/ Spill/	WDR		Grease deposition blockage caused a 225 gallon sewage spill at Eigleberry alleyway to the ground. No waterbody was affected.	None	No further action recommended at this time.		Santa Clara
Gilroy, City of	Gilroy CS		water Quality -> Sanitary Sewer Overflow/	WDR	•	Detached washing machine hose caused a 50 gallon sewage spill at 405 Broadway to the ground. No waterbody was affected.	1	Private lateral spili		Santa Clara
	Gilroy CS		vvater Quality -> Sanitary Sewer Overflow/	WDR		waterbody was affected.		No further action recommended at this time.		Santa Clara
	Goleta User Reclaimed		Water Quality -> Unauthoriz ed Discharge			Irrigation main line break led to 10,000 gal. of recycled water loss onto golf course, approx. 5,000 gal. may have flowed to nearby	Replaced coupler,	A compression coupler on a distribution line failed causing the discharge.		Santa Barbara
	Goleta West		Water Quality -> Sanitary Sewer Overflow/			On March 6, 2008 a 1900 gallon sewage spill occurred at San Miguel Offtract from manhole 79-09-12 to an unpaved vegetated area next to Winchester Canyon Creek. An estimated 190 gallons spilled to creek. Health warnings were posted by SB County Environmental Health for four days. Emergency point repair was performed where a break/offset	and photographs	recommended at this		Santa
Goieta West SD	SD CS	736303	Spill/ water Quality -> Sanitary Sewer	WDR	6-Mar-08	was found in the sewer line. Grease deposition blockage caused a 90 gallon sewage spill at 516 Del Monte Street from a	were taken.	No further action		Barbara
Gonzales, City of	Gonzales City CS	724074	Overflow/	WDR	5-Feb-08	manhole to the ground. No waterbody was affected.	Blockage cleared and spill cleaned.	recommended at this time.		Monterey

Agelmiy.		ege Signus 1821	ioveelia ala	Mic			Darrective Action	Comments	RB Action	County
Hollister, City of	Hollister Domestic WWTP		Water Quality -> Effluent -> OEV	WDR			und and dydiain in	No further action recommended at this time.		San Benito
Laguna Sanitation	Laguna County Sanitation Distr CS	734890		WDR		Grease deposition blockage caused a 2250 gallon sewage spill at 4570 Kenneth from a manhole to the ground. No waterbody was affected.	Blockage cleared and spill cleaned.	No further action recommended at this time.		Santa Barbara
Marina Coast WD	Marina Coast Wd CS		water Quality -> Sanitary Sewer Overflow/ Spill/	WDR		Giggling from manhole west along	Spill and area cleaned up. Discharger maintains Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey
Midland Pacific	Hacienda Hills		Other Requirem ent -> Permit	CONSTW		Violations of General Permit Special Provision for Construction Activity C.1 and C.2. Reports indicated a disturbance greater than one acre without enrolling in the General permit. Also, employees presented an inadequate SWPPP during inspection.		NOV issued 07/05/2006.	NOV	San Luis Obispo
Monterey Co	Monterey - Chualar CS	732054	Condition water Quality -> Sanitary Sewer Overflow/ Spill/	MNSTW2		Break in force main caused a 1000 gallon sewage spill along highway 68, the Monterey Salinas Highway to unknown creek.	Spill and area cleaned. Discharger maintains Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey
Monterey CSA Chualar	Monterey Csa - Chualar CS	741618	Water Quality -> Sanitary Sewer Overflow/ Spill/	WDR	19-Mar-08	Joint failed on force main causing a 300 gallon sewage spill at 120 Spreckels Blvd. into a field. No waterbody was affected.	Spill and area cleaned. Discharger maintains Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey
Pacific Grove, City of	Pacific Grove	741279	Water Quality -> Sanitary Sewer Overflow/ Spill/	MNSTW2	1-Mar-08	Blockage in lateral line caused a 100 gallon sewage spill at Carmel Ave and Lower Light House Ave to the storm drain.	Spill and area cleaned. Discharger maintains Sanitary Sewer Management Plan.	No further action recommended at this time.		Monterey

Agency F	Facility of 1	D			Tale	Sign of the second seco	Confective Action	Comments ***	RIB Action	County
Paso Robles, City of	Paso Robles CS		Quality -> Sanitary Sewer Overflow/ Spill/	WDR		Vandalism caused a 2500 gallon sewage spill at B 18 Bolen Line from manhole along a park walkway to the drainage ditch. No	Cleaned and contained spill.	No further action recommended at this time.		San Luis Obispo
Paso Robles, City of	Paso Robles CS			WDR	14-Mar-08		Cleaned spill and inspected sewer using CCTV to determine cause.	No further action recommended at this time.		San Luis Obispo
Paso Robles, City of	Paso Robles CS	741603	vvater Quality -> Sanitary Sewer Overflow/ Spill/	WDR		Inter and an animal and animal and an animal and animal and an animal and animal and animal animal and animal animal and animal	New locking manhole cover installed.Cleaned and contained spill.	No further action recommended at this time.		San Luis Obispo
Paso Robles,	Paso Robles	747509	Water Quality -> Effluent ->	NPDES		Total dissolved solids violation; reported value is 1125 mg/L; limit value is 1100 mg/L	industrial waste manager to address salts issue. City is also pursuing lower TDS source water from Lake	City is barely over the		San Luis Obispo
City of Pismo Beach City	Pismo Beach	747509	Water Quality -> Sanitary Sewer Overflow/	WDR		Debris blockage caused an 840 gallon sewage spill at Longview and Delano Streets from a manhole to the ground. No waterbody was affected.	Blockage cleared and spill cleaned.	No further action recommended at this time.		San Luis Obispo
San Benito County CSA #22	Cielo Vista Estates	749598	Water Quality -> Effluent ->	WDR		TDS Violation: effluent limit is 30 day average water supply plus 300 mg/L. Reported value is 1095 mg/L compared to the water supply at 463 mg/L.	Staff will address with an NOV.	Increased TDS, sodium, and chloride levels probably due to homeowner use of water softeners.		San Benito
San Benito County CSA #23	Cielo Vista Estates	749600	Water Quality -> Effluent -> CAT1	WDR	11-Mar-08	Sodium Violation: effluent limit is a 30 day average water supply plus 70 mg/L. The reported value is 256 mg/L compared to the water supply at 113 mg/L.		Increased TDS, sodium, and chloride levels probably due to homeowner use of water softeners.		San Benito

Agency	a i i i i i i i i i i i i i i i i i i i				Date	Description:	Corrective Action	Comments	RE Action	County
						****		Increased TDS,]
			Water					sodium, and chloride]
San Benito			Quality ->			The effluent chloride reported		levels probably due to		
County CSA	Cielo Vista		Effluent ->			value is 254 mg/L compared to	Staff will address	homeowner use of		
#24	Estates	749597	CAT1	WDR	11-Mar-08	the water supply at 108 mg/L.	with an NOV.	water softeners.		San Benito
							NOV issued for			
							similar violations.			
							Discharger in	Quarterly effluent		1
								sample represents]
	[funds for a new	monthly average		
							water supply	chloride effluent		
	1						treatment facility in	concentrations for the		
							order to improve	months of Oct, Nov,		
]	1		Water			Effluent chloride concentration	wastewater quality.	and Dec, 2007. Priority		
	San Juan		Quality ->			violation. Reported value is 301	Enforcement Unit is	because serious		
San Juan	Bautista		Effluent ->			mg/L; limit value is 200 mg/L.	currently discussing	violation for MMP		0 0
Bautista, City of	<u>IWWTP</u>	746912	CAT1 Water	NPDES	17-Mar-08	Effluent is >40% of permitted limit.	IMMP.	purposes.		San Benito
			Quality ->				contained and			}
			Sanitary			Root intrusion blockage caused a	cleaned the spill in			
			Sewer		,	35 gallon sewage spill at 710	accordance with the	No further action		
San Luis	San Luis		Overflow/			California to the gutter. No	Sanitary Sewage	recommended at this		San Luis
	Obispo CS	749296		WDR	28-Feb-08	waterbody was affected	Management Plan.	time.	VER	Obispo
Obiopo, Oity Oi	00.000 00	7 10200	<u> </u>							
Į.								Primarily a residential		
							None proposed; it is	community. Elevated		
Į.							difficult to control	salts could result from		
			Water				suspected factors.	water softener use,		
	l		Quality ->			Chloride Violation: Limit is 200	Limits will be	exacerbated by		San Luis
	San Miguel	700004	Effluent ->		40.4400	mg/L and reported value is 240	reviewed during next			Obispo
San Miguel CSD	IWWIP	736301		WDR	10-Mar-08	Operator error, forgot to put lift	update. Spill and area	evaporation.	 	Obispo
			Water Quality ->			station pump back in on position	cleaned up.			1
			Sanitary			causing a 15 gallon sewage spill	Discharger			
			Sewer	1		at Washburn Day Use Park off	developing Sanitary	No further action	1	
San Simeon	San Simeon		Overflow/			Hwy 1, to the ground. No	Sewer Management	recommended at this		San Luis
CSD	Dan Sincon	1		WDR	20-Mar-08	waterbody was affected.	Plan.	time.		Obispo
	les .	7/107/1	IShill/			ITTUICIDOUT TRUS GIICUICU.	[1 mail 1 m	[m:::V:		i
CSD	cs	742741		WUK	20 17127 00					
CSD	cs	742741	Water	WUK	20 Mai 00	Surcharge effect of private				
CSD	cs	742741	Water Quality ->	WUK	20 11121 00	Surcharge effect of private forcemain caused a 20 gallon				
ÇSD	cs	742741	Water Quality -> Sanitary	WDK		Surcharge effect of private forcemain caused a 20 gallon sewage spill at 500 Por La Mar	Contained and	No further action		
Santa Barbara	cs	742741	Water Quality ->	WDK	23 Mar 30	Surcharge effect of private forcemain caused a 20 gallon	Contained and recovered spill.	No further action recommended at this		Santa

Agency					ing pagga Lata satang	Cestolori	Corrective Action	Connaems	RB Action	County
Santa Barbara City PWD	El Estero CS	734451		WDR			Recovered spill and cleaned area.	No further action recommended at this time.		Santa Barbara
Santa Barbara City PWD	El Estero CS			WDR	7-Mar-08	, ,	Contained spill, cleaned area, and inspected sewer line.	No further action recommended at this time.		Santa Barbara
Santa Barbara City PWD	El Estero CS		vvater Quality -> Sanitary Sewer Overflow/ Spill/	WDR		at Stearns Wharf pump station to	Repaired lift station. Contacted health department.	No further action recommended at this time.		Santa Barbara
Santa Barbara City PWD	El Estero CS	727207		WDR		Root intrusion blockage caused a 175 gallon sewage spill at 1125 Arbolado Rd. from a manhole to the ground. No waterbody was affected.	Contained spill and cleaned area, Inspected line.	No further action recommended at this time.		Santa Barbara
Santa Barbara City PWD	El Estero CS	732085	Water Quality -> Sanitary Sewer Overflow/ Spill/	WDR	25-Feb-08	ground. No waterbody was	Contained spill and cleaned area. Recovered 100 gallons.	No further action recommended at this time.		Santa Barbara
Santa Barbara City PWD	El Estero CS	738918	Water Quality -> Sanitary Sewer Overflow/ Spill/	WDR	16-Mar-08	Root intrusion blockage caused a 30 gallon sewage spill at 3536 Los Pinos Drive to the ground. No waterbody was affected.	Contained spill and cleaned area. Inspected line.	No further action recommended at this time.		Santa Barbara
Santa Barbara City PWD	El Estero CS	732086	Water Quality -> Sanitary Sewer Overflow/ Spill/	WDR	25-Feb-08	Upstream blockage caused a 50 gallon sewage spill at 1859 Eucalyptus Hill Road to the ground. No waterbody affected.	Cleaned area and inspected sewer line.	No further action recommended at this time.		Santa Barbara

	acilty		MINISTER STATES		idiase	c.saplen	記事の側に上端をより の の Tanguaga Corrective Action : ***	Comments (1)	RBT Action	County
			Water Quality -> Sanitary Sewer	:		Root intrusion blockage caused a 40 gallon sewage spill at 416 E.	Cleaned area.	No further action		
Santa Barbara City PWD	El Estero CS	734522	Overflow/	WDR		De La Guerra St. to the ground.	recovered volume of spill.	recommended at this time.		Santa Barbara
Santa Barbara			Water Quality -> Sanitary Sewer Overflow/		****	Debris blockage caused a 25 gallon sewage spill at 27 East Carrillo Street to the ground. No	Contained spill and	Private lateral spill. No further action recommended at this		Santa
	El Estero CS	738916	Water Quality -> Sanitary Sewer	WDR		Root intrusion blockage caused a 100 gallon sewage spill at 708 Laurent Street in the residence	cleaned area.	time. No further action		Barbara
Santa Cruz, City of	Santa Cruz City CS	732037	Overflow/ Spill/ water	WDR		and their private lateral. No waterbody was affected	None	recommended at this time.		Santa Cruz
Santa Cruz, City	Santa Cruz City CS	731555	Quality -> Sanitary Sewer Overflow/ Spill/	WDR		a 1200 gallon sewage spill at 2555 Mar Vista / Soquel Drive out of manhole into a drainage canal.	Vaccuumed manhole, flushed line, raked up and removed solids, line to be televised	No further action recommended at this time.		Santa Cruz
Santa Cruz, City	Santa Cruz City CS	731548		WDR		Grease blockage caused a 300 gallon sewage spill at 3131 Soquel Drive through a manhole into a storm drain which feeds Rodeo Creek.	Freshwater added to dilute, some sewage recovered by vaccuum. Line to be televised.	No further action recommended at this time.		Santa Cruz
Santa Cruz, City	Santa Cruz City CS	732039	water Quality -> Sanitary Sewer Overflow/ Spill/	WDR		may have been carried to creek		No further action recommended at this time.		Santa Cruz
Santa Cruz, City	Santa Cruz		Water Quality -> Sanitary Sewer Overflow/	WDP		Power failure caused a 1200 gallon sewage spill at Hwy 226/Fallen Leaf Way from Station #3, down hill across (under) road.	. *	No further action recommended at this		Santa Cruz
	City CS	731556		WDR	14-Feb-08	No waterbody was affected.	power.	time.		Santa

united that 18 years Agency		oskaldkiejs Tydysiski	Misaranana			Descriptor	Corrective Action	Comments ***	RE III	County
Santa Cruz, City		734448	Water Quality -> Sanitary Sewer Overflow/ Spill/	WDR		A breaker was imposed at a pump station causing a 50 gallon sewage spill at 607 Sand dollar Lane to the street, into the storm drain. Spill reached the beach where it was absorbed by the sand. The spill did not reach the	Area was washed down and cleaned up. Failed pump was replaced.	No further action		Santa Cruz
Santa Cruz Cnty	Santa Cruz County CS	742737		WDR		Rags blockage caused a 100 gallon sewage spill at 4540 Soquel Wharf Road into storm drain. Storm drain flows to Soquel Creek.	truck.	No further action recommended at this time.		Santa Cruz
Santa Cruz,	Santa Cruz		Water Quality -> Sanitary Sewer Overflow/			Roots and rags created a blockage causing a 100 gallon sewage spill at 2701 Estates Drive to the ground. No waterbody	hydroflushed, surface materialsm were racked up and removed, line to be	No further action recommended at this		
County of Santa Cruz CSA	County CS Rolling Woods	734435	Spill/ Water Quality -> Effluent ->	WDR	11-Feb-08	was affected. Nitrogen Reduction Violation:	televised Discharger will modify plant	time.		Santa Cruz
#10 Santa Maria, City of	Subdivision City of Santa Maria CS	749881 731975	vvater Quality -> Sanitary Sewer Overflow/	WDR WDR		In nitrogen. Broken clean out pipe caused a 750 gallon sewage spill at Panaderia Mana, 503 Broadway, at the back parking lot of the restaurant into the alley. No waterbody was affected.	its effectiveness Spill area cleaned up, line cleared.	No further action recommended at this time.		Santa Cruz Santa Barbara
Santa Maria, City of	City of Santa Maria CS	734850	Water Quality -> Sanitary Sewer Overflow/	WDR		Grease deposition blockage caused a 750 gallon sewage spill at 100 Portland Drive from manhole to curb and gutter then to storm drain. No waterbody was		No further action recommended at this time.		Santa Barbara
Scotts Valley, City of	Scotts Valley	738473		WDR		Debris blockage in sewer line caused a 90 gallon sewage spill at 121 Sunset Terrace to back yard. Spill flowed to Granite Creek Rd. and into storm sewer. Storm drains to Carbonero Creek.	Truck vacuumed line, inspection found no visible adverse effects, samples found no pollution.	No further action recommended at this time.		Santa Cruz
Sunnyslope CWD	Ridgemark Estates WWTP	753157	Water Quality -> Effluent -> CAT1	WDR	5-Feb-08	Effluent chloride violation; max permit limit is 300 mg/L; reported value is 560 mg/L in RM#1	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito

Abbreviations: Collection System - CS Notice of Violation - NOV

Verbal Action - VER

Cleanup and Abatement Order - CAO Waste Discharge Requirments - WDR

	Facily 1					Descripto	Conecute Action	Comments 11	RE	County
Sunnyslope CWD	Ridgemark Estates WWTP	753832		WDR	5-Mar-08	Sodium Violation: Limit is 300 mg/L and the reported value is 370 mg/L in RM#1.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753833		WDR		Effluent chloride violation; max permit limit is 300 mg/L; reported value is 520 mg/L in RM#1	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753834		WDR		Effluent chloride violation; max permit limit is 300 mg/L; reported value is 610 mg/L in RM#2	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753159	Water Quality -> Effluent -> CAT1	WDR		TDS Violation: Limit is 1500 mg/L. Reported value indicates 1700 mg/L in RM#1.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP			WDR	5-Mar-08	TDS Violation: Limit is 1500 mg/L. Reported value indicates 1600 mg/L in RM#2.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753839	Water Quality -> Effluent -> OEV	WDR	5-Mar-08	Ammonia Violation: Limit is 10 mg/L. The reported value is 11 mg/L in Rm #1.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753840	Water Quality -> Effluent -> CAT1	WDR	5-Feb-08	BOD Violation: Limit is 60 mg/L. The reported value indicated 81 mg/L in RM#2.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753158	Water Quality -> Effluent -> CAT1	WDR	5-Feb-08	Effluent chloride violation; max permit limit is 300 mg/L; reported value is 610 mg/L in RM#2	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753196	Water Quality -> Effluent ->			TDS Violation: Limit is 1500 mg/L. Reported value indicates 1900 mg/L in RM#2.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753831	Water Quality -> Effluent -> CAT1	WDR		Sodium Violation: Limit is 300 mg/L and the reported value is 390 mg/L in RM#1	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito
Sunnyslope CWD	Ridgemark Estates WWTP	753838	Water Quality -> Effluent -> OEV	WDR	5-Feb-08	Ammonia Violation: Limit is 10 mg/L. The reported value is 31 mg/L in Rm #1.	Formal explanation and corrective actions forthcoming.	NOV will be sent to discharger.		San Benito

Acestic						Securitor:	Corrective Action 1	Comments	RB	County
In the Late Constitution of the Constitution o	Ridgemark	AND THE PARTY OF T	Water Quality ->			Sodium Violation: Limit is 300	Formal explanation			
Sunnyslope	Estates		Effluent ->			mg/L and the reported value is	and corrective	NOV will be sent to		
CWD	WWTP	753836		WDR	5-Feb-08	460 mg/L in RM#2	actions forthcoming.	discharger.		San Benito
			Water			0	Carrel avalenches			
0	Ridgemark		Quality ->			Sodium Violation: Limit is 300	Formal explanation and corrective	NOV will be sent to		
Sunnyslope	Estates WWTP	753837	Effluent ->	WDR		mg/L and the reported value is		discharger.		San Benito
CWD	VVVVIP	100001	Water	WUK	3-Wai-06	420 mg/L in RM#2.	actions formconning.	discriarger.	·	San Defino
	Ridgemark		Quality ->	1		Total Suspended Solids Violation:	Formal explanation			
Sunnyslope	Estates		Effluent ->			Limit is 60 mg/L. The reported	and corrective	NOV will be sent to		
CWD	WWTP	753828		WDR	5-Feb-08	value indicated 63 mg/L in RM#1.	actions forthcoming.	discharger.		San Benito
			Other			-				
			Requirem			Maladan of Osmanl Banki				
T-'			ent ->			Violation of General Permit		NOV issued		San Luis
Trimark Pacific	La Terraza at	794606	Permit	CONSTW		Special Provision for Contruction Activity C.1.		06/20/2006.	NOV	Obispo
Homes	Las Lomas	/31000	Condition	COMPTAN	25-Feb-06	Activity C.1.		00/20/2000.	NOV	Chispo
			Water			Pump station failure due to switch				
			Quality ->			turned off caused a 200 gallon				1
			Sanitary			sewage spill at AAA/Applebee™s		<u> </u>	-	
			Sewer	!		Lift Station to a vegetated ditch.		No further action		
Watsonville,			Overflow/	1		Name of impacted surface waters		recommended at this		l
City of	Watsonville CS	739299	Spill/	WDR	21-Mar-08	not available.	Little water flow	time.	ļ	Santa Cruz